Work Ord Thursday, Man	-						
Item ID: Revision ID:	D3272-1		Accept		Setup	Start	
Item Name:	Step	,		•		Stop	
Start Date:	3/10/2011	Start Qty: 10.00		Cust Item ID:			
<b>Required Date:</b> 3/18/2011			Customer:				
Reference:							
Approvals:	Process Pl	an:	Date: 11-03-10 tooling:	Date:	Run	Start	
	QC:		Date: $SPC(Y/N)$ :	Date:		Stop	

Sequence ID/ Operation Tool# Plan Tool ID Reject Set Up/ Accept Reject Insp. Work Center ID Description Qty Number Stamp Code Qty **Run Hours Revision Nbr** Draw Nbr D3272 Rev B 100 0.00 Large Fab

Large Fab 0.00 Memo Large Fab

\*\*\*SQUARE ONE END BEFORE CUTTING OTHER END\*\*\*

1-Cut D2622-120 extrusion to 116.25" long as per Dwg D3272 using cutting

table setup DT 8185-2A

2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets.

3-Deburr

110 QC6- Inspect dimensions to drawing 0.00

Memo

Quality Control

0.00

Page 1



W/O: WORK ORDER CHANGES  DATE STEP PROCEDURE CHANGE By  PROCEDURE CHANGE BY	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		Chief Eng /	Approval QC Inspector		
Port No.					
Port No.					
Port No.					
Port No.	_				
Port No. DAD # South Cots years NCD: Year N					
Port No. DAD # Fould Colombia					
Part No: PAR #: Fault Category: NCR: Yes N	No DQA:	Date: _			
Resolution: Disposition: QA: N/C Clo					
NCR: WORK ORDER NON-CONFORMANCE (NCR)	)				
DATE STEP Description of NC Section A Section B Initial Action Description Sign &	Verification	Approval Chief Eng	Approval		
Section A Initial Action Description Sign & Date	Section C		QC Inspector		
	-				

#### Work Order ID 67196

Thursday, March 10, 2011 8:48:28 AM



Page 2

Item ID:

D3272-1

Accept

Setup Start

Stop



**Revision ID:** 

Start Date:

Item Name: Step

3/10/2011

**Start Oty: 10.00** 

Req'd Qty: 10.00



Cust Item ID:

**Customer:** 

Reference:

**Approvals:** 

**Process Plan:** 

Date:

Tooling:

Date:

Tool ID

Run

Start

Stop



Sequence ID/

Work Center ID

Required Date: 3/18/2011

QC:

Date:

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Tool # Plan Accept

Code

Reject Qty

Reject Number

Insp. Stamp

120

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location: WA

0.00 0.00 1211.03.17 10 B

Qty

130

QC21- Final Inspection - Work Order Release

0.00



Quality Control

Memo

Memo

0.00

		·								
W/O:		<u> </u>	WC	RK ORDER CHANG	GES				4	
DATE	STEP	PROCEDURE CHANGE				Da	ate Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cate	gory:	NCR: Ye	s No	DQA:	Date: _		
Resolution:			Disposition: QA: N/C Close			Closed	sed: Date:			
NCR:		,	WORK ORDI	R NON-CONFORM	ANCE (N	CR)				
DATE	STEP Description of NC Section A	Description of NC	Initial	Corrective Action Section B		n &	/erification	Approval	Approval	
		Section A	Chief Eng	Action Description Chief Eng		ite	Section C	Chief Eng	QC Inspector	
	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4									

### Picklist Print

Thursday, March 10, 2011 8:48:34 AM

Work Order ID: 67196

Parent Item: D3272-1

Parent Item Name:

Component Item ID/

Step



Location

WA

Start Date: 3/10/2011

Required Date: 3/18/2011

Page 1

Status

**Start Qty: 10.00** 

Required Qty: 10.00

Comments:

IPP Rev:A

Item ID

Replacement Mfg/

New Issue 07-06-09

Manufactured

Purch

J6-U9	JLM
-	

3-02	PENT

No

Bin	Primary	Last
Item	Location	Location


Route Seq ID

100

Each

Qty on

69.5110





Total



D2622-120C

Item Name

Step Extrusion

Loc Otv	Loc Code	

	69.511
55214	1.92
58544	1
61208	4.724
64409	61.867

Loc Code

W/O:		·	WC	ORK ORDER CHANG	GES					
DATE STEP		PR	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
***************************************										
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA:	Date: _			
Resolution:			Dispositio	າ:	QA: N/C CI	C Closed: Date:				
NCR:			WORK ORDI	R NON-CONFORM	ANCE (NCF	R)	111111111111111111111111111111111111111			
DATE	STEP Des	STEP Description of NC Section A			tion B	Verification	Approval Chief Eng	Approval QC Inspector		
DATE			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C				
***************************************										
,										
						-				



DESIG	p	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	· · ·
CHECK	(ED	APPROVED	DRAWING NO.	REV. B
(	E	世	D3272 SHEET	1 0F 3
DATE			TITLE .	SCALE
07.0	)5.18		STEP ASSEMBLY, HI LONG	NTS
Α		04.03.01	NEW ISSUE	
В		07.05.18	D3272-1 WAS D2622-120	

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D3272-041	STEP ASSEMBLY, HIGH LONG (LH)
	Х	D3272-042	STEP ASSEMBLY, HIGH LONG (RH)
1	1	D3065-041	LEG ASSEMBLY
2	2	D3066-1	SPACER
2	2	D3067-1	END PLATE
2	2	D3219-1	SUPPORT
1	1	D3272-1	STEP
16	16	MS20600AD4W4	RIVET
1			

# **GENERAL NOTES:**


- 1) D3272-041 SHOWN. FOR D3272-042, INSTALL D3219-1 SUPPORT OPPOSITE SIDE
- 2) WELD PER DART QSI 004
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005.4.1 POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3 **BLACK ANTI-SKID PAINT PER DART QSI 005 4.4**
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- 5) ALL DIMENSIONS ARE IN INCHES UNLESS OTHERWISE NOTED.
- 6) BREAK ALL SHARP EDGES 0.005 TO 0.010 MAX.

SHOP COPY RETURN TO ENGINEERING UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER NO. 4796 RS 11-03-10

Copyright © 2004 by DART AEROSPACE LTD


THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.


W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Categ	jory:	_ NCR: Ye	s No DO	)A:	Date: _		
			Disposition: QA: N/C Closed: D						_ Date:	
NCR:		1	WORK ORDE	R NON-CONFORM	ANCE (NO	R)				
DATE	OTED	Description of NC		VA			ification Approval	Approval		
DATE	SIEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	ı&∣ <sub>Sec</sub>	tion C	Chief Eng	QC Inspector	
									_	
						1				



	•										
W/O:			W	ORK ORDER CHANG	SES						
DATE	STEP	PROCEDURE CHANGE				Date	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
-											
Part No	<b>1</b>	PAR #:	Fault Category: N			NCR: Yes No DQA: Date:					
	R	esolution:	Dispositio	QA: N/C Closed: Date:							
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NO	R)					
DATE	STEP	Description of NC Section A			tion B	Ver	Verification	Approval	Approval		
			Initial Chief Eng	Action Description Chief Eng	Sigr Da	i <b>&amp;</b> S	ection C	Chief Eng	QC Inspector		
*****		_									
									To the state of th		
	1	1	1			1		1	1		







Copyright © 2004 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:			V	ORK ORDER CHANG	ES				- 111	<b>₹</b> . •
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				,						
								,.		
				*					•	
Part No:		PAR #:	Fault Category:			: Yes	No DQ	A:		
	R	esolution:	Dispositi	on:	QA: N/C Closed:					
NCR:		\	WORK OR	DER NON-CONFORMA	NCE	(NCR	)			•
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification			Approval	Approval
			Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
,										
							•			
÷.										
			÷	·						
			-							